

Figure 7: Width of crack 1, on the eastern shoulder of Chances Peak, between December 1996 and February 1997. The length of the measurement line across the crack is shown in cm.